

Place ring handle with latch horizontally

on gate where required. Make sure latch overlaps gate frame by 40-50mm. Mark where spindle should go and drill a 12mm hole for spindle into gate.

2. Insert spindle into hole and into rear of

each handle on each side of gate. Mark out

- holes for both handles on gate.

 Note: Spindle may need to be cut for gates less than 4 inches thick.
- Remove handles with spindle and drill pilot holes for screws into gate. Replace handles with spindle and fix to gate using screws provided.
- 4. Slide keep over latch. Mark out holes for keep on gate.
- Remove keep and drill pilot holes for screws into gate. Replace keep and fix to gate using screws provided.
- 6. Place keep plate on frame. Make sure latch rests horizontal and securely in keep. Mark out holes for keep plate on frame.
- Remove keep plate and drill pilot holes for screws into frame. Replace keep plate and fix to frame using screws provided.